



Mars Labs
29 C Street
Laurel, MD 20707

September 16, 2015

Document # SB-2323

Service Bulletin

TCS - Titan Control Software v3.1.8

Applicability: This new release is recommended for all Titan product users.

Description: Titan Control Software version 3.1.8 incorporates the following feature enhancements and bug fixes:

1. Corrected an issue with Wheel Force Transducer data (gap issue)
2. Implemented Poisson ratios for strain gauge sensors
3. Added Gadget Driver to the TCS Installer (used by the new CPX Expander, New CPU, and Titan II devices)
4. Welcome screen selections are now listed by connection type (USB, Ethernet)

TCS v3.1.8 is available as an *Installer* that includes all required support files as well as an update to the embedded User Manual that provides context-sensitive help.

Update: Download TCS v3.1.8 from the Mars Labs Knowledge Base:

<http://marslabs.com/wiki/doku.php>

Note that you will need a login name and password to download the update – please contact Mars Labs to obtain login credentials if you have not already been supplied the information.

Help: For additional information or assistance, please contact:

Mars Labs
Phone: 301-470-3278
Email: support@marslabs.com
www.marslabs.com